Survey No. 68-4-41

Maryland Historical Trust State Historic Sites Inventory Form

DOE __yes __no

1. Nam	e (indicat	ce preferred name)		
historic				
and/or common	Riverdale	Shoe Repair / Secon	nd Time Around Co	onsignment Shop
2. Loca	ation			
street & number	6237-41 Ba	ltimore Ave.		not for publication
city, town	Riverdale	vicinity of	congressional district	5
state	Maryland	county	Prince George	's
3. Clas	sificatio	n		
Category district building(s) structure site object	Ownership public private both Public Acquisiti in process being conside not application	x yes: restricted ered yes: unrestricted	Present Use agriculture _X_ commercial educational entertainment government industrial military	museum park private residence religious scientific transportation other:
4. Own	er of Pro	perty (give names a	nd mailing addresse	es of <u>all</u> owners)
name	Louis and	Samuel Caruso / Dom	inic and Agatha	Bruno
street & number	- see at	tached sheet -	telephone n	no.:
city, town		state	and zip code	
5. Loca	ation of L	egal Descripti	on	
courthouse, regis	stry of deeds, etc.	Prince George's Co	unty Courthouse	liber 5625
street & number		Main Street		folio 447
city, town		Upper Marlboro	state	Maryland
6. Rep	resentati	on in Existing	Historical Surv	veys
title				
date			federal sta	ite county loca
depository for su	rvey records			
city, town			state	

7. Description

Survey No.

-5-157-4-11

Condition excellent	deteriorated	Check one unaltered	Check oneX original s	iite	
good fair	ruins unexposed	_X_ altered	moved	date of move	

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

6237-41 Baltimore Avenue is a two story commercial building located at the southwest corner of the Baltimore Avenue/East-West Highway intersection. At present it houses two retail establishments - the Riverdale Shoe Repair Shop and the Second Time Around Around consignment shop.

The building is rectangular in plan, with the shorter end facing west, toward Baltimore Avenue. This main facade reflects the dual ownership of the building with different treatments on each half. The general elements are similar on both halves: a light brown brick facade with first level storefronts. The halves each have two entries - the outer doors servicing the first level shops and the center doors servicing the upper level. Between the entries on each side are square bay windows for display purposes. Each opening on the first level has a transom window above. The second level has six six-over-one sash windows, three on each side. The brick is patterned in a stretcher bond with row-lock coursesdirectly below the cornice and the second level windows. Additionally, there are decorative courses above the first level transoms, above the second level windows and below the cornice.

The differences in treatment for the two halves are mainly cosmetic. The southern half uses a black paint on the trim of the shop's door and display window. It also uses black shutters on the second level. The remainder of the trim is beige. On the northern half, all trim is beige and there are no shutters on the second level. The doors vary from full glass panelled to wood panelled with glass panels at the top to a solid door with a vertical glass panel by the knob.

The north facade, towards East-West Highway, has a stucco facing. It has a stepped parapet roof and several small window openings on the second level. This facade is marked by a mural of an old man and a boy seated on the steps of a Victorian home.

8.	Sign	ifican	ce
	_		

Survey No. PG #68-4-41

Period prehi 1400 1500 1600 1700 1800 1900-	-1499 -1599 -1699 -1799 -1899	Areas of Significance—C archeology-prehistoric agriculture architecture art commerce communications		Iandscape architectur Iaw Iiterature Immunitary Immunit	re religion science sculpture social/ humanitarian theater transportation XXother (specify) local history
Specific	dates	1925-6	Builder/Architect		
check:	ar Appli		BCD ABCD _nationalstate		
	•			•	

Prepare both a summary paragraph of significance and a general statement of history and support.

6237-41 Baltimore Avenue is a typical example of a two-part commercial block, which were common from the 1850's to the 1950's, especially in towns that developed along streetcar lines. While Riverdale was platted in 1889 and incorporated as a town in 1920, this building was constructed in 1925-6 by J. Berlin, who also built 6231-3 Baltimore Avenue, nexy door. At this time, Route One (Baltimore Ave,) was the main road from Washington to the north. It had also just been incorporated into U.S. Route 1 - the main north-south arterial on the east coast, stretching from Maine to Florida. This designation encouraged a tremendous amount of commercial buildup along the road to service travelers. 3

Berlin also constructed a store immediately north of this building, but it was removed for the extension of East-West Highway in the 1960's. Berlin sold the northern half of lot 2 in 1931 to E. Lacroix. This sale included only the northern half of this building, presently occupied by the shoe repair shop. The southern half of Lot 2 was sold to M. and G. Gorin in 1932. This included the southern half of this building as well as 6231-3 Baltimore Avenue. 5

The mural on the northern facade was mounted in 1977 as part of the Prince George's County Murals Project, sponsored by the Maryland/National Capital Park and Planning Commission. The program was the first in the country to promote the use of murals in a suburban setting. The artist, John Ford, was the grandson of former Riverdale councilmember Walter Ford. The mural depicts an old man and a young boy sitting on the steps of a Victorian home, Symbolic of Riverdale architecture and the relationship between young and old. 7

10. Geo	graphical Data			
Quadrangle name	do NOT complete UTM refere		Quadrangle scale	
Zone Easting	Northing	B Zone E	asting Northing	
C		D		
	description and justification d counties for properties overlap	ping state or coun	ty boundaries	
state	code	county	code	
				e
state	code	county	code	· · · · · · · · · · · · · · · · · · ·
	n Prepared By	county	code	
11. Forn			code	
11. Forn	n Prepared By	udent	code March, 1990	
	Robert D. Rivers, st	udent	March, 1990	

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

Shaw House 21 State Circle

Annapolis, Maryland 21401

(301) 269-2438